

## Caution · Notice

1. Sensor output is defined by generated electrical charge.  
Please use this shock sensor with charge amplifier circuit.
2. Please do not apply DC voltage for this shock sensor.
3. Please inquire Murata for washing conditions.